



NITOL MOTORS LTD

(SERVICE AND PARTS)



100 TONGI INDUSTRIAL AREA, GARZIPUR

SOFTWARE DOCUMENTARY

(IT DIVISION)



REF : IT CIRCULAR_REF_NML_SE_IT_SOFT_15042013_50

AGENDA

Labour Jobs Check



Labour Job Check



Labour Job Check

Labour Entry

1. Type JC and Load

Job Card No: 112253
 KM: 0
 Chesis: MAT38653477R34812
 Customer Name: HAJI MD, RAFIQUE
 Bay No: 12

Vehicle Reg. No: CMDA111111
 Model No: LP 909/49 MA
 Dealer: 14
 Address: ENAYET BAZA
 Bay Allocation Time: 4/15/2013 12

Standard Jobs

Issue Type: Chargeable
 Model: 509
 Main Group: A/C SYSTEM
 Job: A/C SYSTEM
 Group/ Section: CHASSIS & SUSPENSION

2. Select Main Group

FRONT AXLE

Reset Show Warranty Job's Info

Standard Jobs

Issue Type: Chargeable
 Model: 509
 Main Group: FRONT AXLE
 Job: Replacement of Tie rod Ends (Including wheel alignments)

3. Select Job

Group/ Section: Wheel bearing adjustment / hub (includes removing and refitting wheels)
 Replacement of Tie rod Ends (Including wheel alignments)
 Anchor plate / Torque Plate Replacement per wheel
 King Pin/ bush replacement / Side
 Removal and reinstallation of one stub axle on I-beam
 King Pin/ bush replacement both Side
 Front both wheel bearing adjustment / Hub greasing

New window


Check Parameters For This Labour

SL	P.Code	Description	<input type="checkbox"/>
1	456	King Pin Free Play check	<input checked="" type="checkbox"/>
2	457	Hubs Free Play check	<input checked="" type="checkbox"/>
3	458	Tie Rod and Drug link rod check	<input checked="" type="checkbox"/>
4	459	Wheel Alignment check	<input type="checkbox"/>
5	460	Brake Drum clearance check	<input checked="" type="checkbox"/>
6	461	Torque Plate bolt check	<input checked="" type="checkbox"/>
7	462	Returning Spring with Brake shoe check	<input checked="" type="checkbox"/>
8	463	S-cam shaft check	<input type="checkbox"/>
9	464	S-cam bush check	<input type="checkbox"/>

4 Check



Report : Labour Job Check



Labour Checking List




Report ; Labour Job Check


1. Date Wise



Labour Jobs Check Report

Date Wise Job Card Wise

Date Wise

Date From : 

Date To : 

 NITOL MOTORS LTD(SERVICE) 100 TONGI I/A GAZIPUR Labour Checking List 			
Job Card No: 112248			
SLNo	Jobs Checked Points	Checking Date	Checked
1	Check the propeller shaft nut bolt	03-Apr-2013	Yes
2	Check the cupling flange (Tail,Center Bearging,Gear Box)	03-Apr-2013	Yes
3	Greasing Piont check	03-Apr-2013	No
4	Check the propeller shaft alignment	03-Apr-2013	No
5	Check the CJ bearing	03-Apr-2013	Yes
6	Check the propeller shaft nut bolt	03-Apr-2013	Yes
7	Greasing Piont check	03-Apr-2013	Yes
8	Check the cupling flange (Tail,Center Bearging,Gear Box)	03-Apr-2013	No
9	Check the CJ bearing	03-Apr-2013	No
Job Card No: 112250			
SLNo	Jobs Checked Points	Checking Date	Checked
10	Check the propeller shaft nut bolt	10-Apr-2013	No
11	Greasing Piont check	10-Apr-2013	No
12	Check the cupling flange (Tail,Center Bearging,Gear Box)	10-Apr-2013	Yes
13	Check the propeller shaft alignment	10-Apr-2013	Yes
14	Check the CJ bearing	10-Apr-2013	Yes
Job Card No: 112251			
SLNo	Jobs Checked Points	Checking Date	Checked
15	Coolent Leakage check	10-Apr-2013	Yes
16	Coolent level check	10-Apr-2013	No
17	Thermostate check	10-Apr-2013	Yes
18	Fan Belt tension check	10-Apr-2013	No
19	Hose pipe & clamp check	10-Apr-2013	Yes
20	Radiator check & Drain plug check	10-Apr-2013	No
21	Heat meter check	10-Apr-2013	No
22	Steering box hose & clamp check	10-Apr-2013	Yes
23	Check free rotation of steering wheel.	10-Apr-2013	Yes
24	Check the level & leakage of oil	10-Apr-2013	Yes



Report ; Labour Job Check



2. JobCard Wise

Labour Jobs Check Report

Date Wise Job Card Wise


Job Card Wise

Job Card No :

 **NITOL MOTORS LTD(SERVICE)** 
100 TONGI I/A GAZIPUR
Labour Checking List

Job Card No: **112253**

SLNo	Jobs Checked Points	Checking Date	Checked
1	King Pin Free Play check	15-Apr-2013	Yes
2	Hubs Free Play check	15-Apr-2013	Yes
3	Tie Rod and Drug link rod check	15-Apr-2013	Yes
4	Wheel Alignment check	15-Apr-2013	No
5	Brake Drum clearance check	15-Apr-2013	Yes
6	Torque Plate bolt check	15-Apr-2013	Yes
7	Returning Spring with Brake shoe check	15-Apr-2013	Yes
8	S-cam shaft check	15-Apr-2013	No
9	S-cam bush check	15-Apr-2013	No



THANK YOU

